



U.S. ENVIRONMENTAL PROTECTION AGENCY
 POLLUTION/SITUATION REPORT
 Hover Street Drum - Removal Polrep
 Initial and Final Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
 Region VIII

Subject: POLREP #1
 Initial/Final
 Hover Street Drum
 A8L1
 Longmont, CO
 Latitude: 40.0806470 Longitude: -105.0746070

To: Laura Williams, EPA

From: Hays Griswold, OSC

Date: 10/14/2015

Reporting Period: 08/22/2015

1. Introduction

1.1 Background

Site Number:	A8L1	Contract Number:	
D.O. Number:		Action Memo Date:	
Response Authority:	CERCLA	Response Type:	Emergency
Response Lead:	EPA	Incident Category:	Removal Action
NPL Status:	Non NPL	Operable Unit:	
Mobilization Date:	8/22/2015	Start Date:	8/22/2015
Demob Date:	8/22/2015	Completion Date:	8/22/2015
CERCLIS ID:		RCRIS ID:	
ERNS No.:		State Notification:	
FPN#:		Reimbursable Account #:	

1.1.1 Incident Category

This was a classic emergency response under CERCLA.

1.1.2 Site Description

The drum was abandoned along a road in a residential area in Longmont, Colorado

1.1.2.1 Location

The site is located at 2215 Pike Road, Longmont in Kiowa County, Colorado

1.1.2.2 Description of Threat

The drum, suspected to contain hazardous substances, was left abandoned by unknown an perpetrator (s).

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

The Longmont Fire Department did some preliminary testing on the contents of the drum and then called Emergency Response. OSC Hays Griswold was sent to the scene and mobilized the ERRS contractor to overpack and dispose of the barrel with unknown contents.

Longmont police guarded the scene until the OSC arrived.

The barrel contained a hard, dry substance and possibly a liquid in the bottom of the container.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

On August 22, the Longmont Fire Department called EPA's Emergency Response after trying to contact the property owner concerning an abandoned drum. The drum was a 55-gallon blue poly drum with an open top ring closure and had a bung opening. It was not leaking.

The contents of the barrel were not known. Emergency Response and Removal Services (ERRS) donned safety gear and slipped the barrel into a poly overpack drum and transported it to their facility for characterization and disposal

2.1.2 Response Actions to Date

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

2.1.4 Progress Metrics

<i>Waste Stream</i>	<i>Medium</i>	<i>Quantity</i>	<i>Manifest #</i>	<i>Treatment</i>	<i>Disposal</i>

2.2 Planning Section

2.2.1 Anticipated Activities

The barrel and its contents will be taken to an authorized facility for disposal.

2.2.1.1 Planned Response Activities

No further actions are required.

2.2.1.2 Next Steps

2.2.2 Issues

2.3 Logistics Section

No information available at this time.

2.4 Finance Section

No information available at this time.

2.5 Other Command Staff

No information available at this time.

3. Participating Entities

No information available at this time.

4. Personnel On Site

No information available at this time.

5. Definition of Terms

No information available at this time.

6. Additional sources of information

No information available at this time.

7. Situational Reference Materials

No information available at this time.